

Fig. 28.2 Approximate stress factor for curved beams.



Fig. 28.3 Notation for a working portion of a machine hook.